



**Dalmeny Chord
Permanent Way Upgrade
to 100MPH PSR**

Possible requirement for
slope treatment works to cuttings
and embankments. In addition, some
bridge clearance works required.
Complete works scope not defined
at present.

Based upon the Ordnance Survey mapping (circa 2001) with permission of the
Controller of HMSO © Crown copyright.
Unauthorised reproduction infringes Crown copyright and may lead to
prosecution or civil proceedings. CEC (Licence No. LA09027L)

| | | | | |
|-------------------|-------------------|-------------------|--------------------|----|
| Project Manager: | | | | |
| Email: | | | | |
| Telephone: | | | | |
| Project No: | | Rev / Date | Description | Dm |
| ELF / Mileage: | | Issue Status: | | |
| Scale: | 1:2500 | | | |
| Dwn: M.Mckenzie | Chkd: A.Macdonald | Appd: G.Coudts | Revision | |
| Date: 08 May 2005 | Date: 08 May 2005 | Date: 08 May 2005 | SW-PW-CV-DRG-10174 | |
| | | | FOR INFORMATION | |
| | | | P01 | |

Scott Wilson
www.scottwilson.com

Halcrow
www.halcrow.com

Scott Wilson Halcrow JV
Buchanan House
58 Port Dundas Road
Glasgow G4 0HG
Telephone 0141 335 3223
Fax 0141 335 2757

ENGINEERING LAYOUT

FIGURE 2.6

EDINBURGH AIRPORT RAIL LINK

Client

the tid
Verify House
19 Haymarket Yards
Edinburgh
EH12 5BH
Tel 0131 622 8300
www.thetid.co.uk