



**Dalmeny Chord Permanent Way Upgrade to 100MPH PSR**

Possible requirement for slope treatment works to cuttings and embankments. In addition, some bridge clearance works required. Complete works scope not defined at present.

Based upon the Ordnance Survey mapping (circa 2001) with permission of the Controller of HMSO © Crown copyright. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings. CEC (Licence No. LA09027L)

<p><b>EDINBURGH AIRPORT RAIL LINK</b></p> <p>the lid Verify House 19 Haymarket Yards Edinburgh EH12 5BH Tel 0131 622 8300 www.edinburgh.co.uk</p>	<p><b>ENGINEERING LAYOUT</b></p> <p><b>FIGURE 2.5</b></p>		<p><b>Scott Wilson</b> www.scottwilson.com</p> <p><b>Halcrow</b> www.halcrow.com</p> <p>Scott Wilson Halcrow JV Buchanan House 58 Port Dundas Road Glasgow G4 0HG Telephone 0141 335 3223 Fax 0141 335 2757</p>	<p><b>FOR INFORMATION</b></p> <p>Dw: M. McKenzie   App: G. Coult Date: 08 May 2005   Date: 08 May 2005</p>	<p>Project Manager: Email: Telephone: Project No: ELF7 Mileage: Scale: 1:2500</p>	<p>Rev / Date Description Em Chk / App</p>
	<p>Client</p>	<p>Drawing Title</p>		<p>Drawing No: SW-PW-CV-DRG-10173</p> <p>Revision P01</p>		